# **Fast Valve Control Valve**

Symptom	Correction
Control valve to slow or too fast	<ul> <li>Verify the setting in the monitor should be 743 for Raven Controllers.</li> <li>Increase or decrease the first digit between 1-9. 1 being the fastest and 9 being the slowest.</li> </ul>
Control valve always over shooting or under shooting intended rate	<ul> <li>Verify the setting in the monitor should be 743 for Raven Controllers</li> <li>Increase or Decrease the second digit between 1-9. 1 being fastest and 9 being the slowest.</li> <li>Explanation of the 2<sup>nd</sup> digit on the valve calibration</li> <li>% away from target before the valve slows down 1=10%, 2=20% 3=30% and so on.</li> </ul>
Control Valve not responding to rate changes	<ul> <li>Verify the setting in the monitor should be 743 for Raven Controllers.</li> <li>Increase or Decrease the third digit between 1-9. 1 being the fastest and 9 being the slowest.</li> <li>Explanation of the 3<sup>rd</sup> digit on the valve calibration.</li> <li>% of deviation allowed before the valve responds 1=1% 2=2% 3=3% and so on</li> </ul>
Rate does not change in either manual or automatic mode	<ul> <li>Check cables for breaks or bare wires</li> <li>Verify voltage on the Flow Cables and Extensions</li> <li>If cables are good replace Motor drive on Fast Valve. Part # 1-063-0172-982 (Motor Only)</li> </ul>

### Fast Valve Troubleshooting

## Keyway 12 o'clock 2 o'clock ground

4 o'clock increase 8 o'clock decrease 2 to 10 -12 volts 2 to 8 master off 12 volts 2 to 4 master on 12 volts On 16 Pin Harness Pin 1 ground Pin 14 constant 12 volts Pin 3 increase Pin 4 decrease

10 o'clock constant 12 volts

1 to 3 - 12V Master on 1 to 4 - 12V Master off

On 37 Pin Harness

Pin 1 Ground Pin 3 Constant 12 volts Pin 15 decrease Pin 16 increase

1 to 15 - 12V Master off 1 to 16 - 12V Master on Rate controller Specific Issues

### **Topcon Apollo**

 Reverse Valve Direction is enabled and Fast valve cap is on the harness

#### JD GS1/GS2 Rate Controller

- Fast Close Valve checked
- 493 cal number Maxflow VRC II
- Fluctuations in rate change 743 to 543 Coolers

#### Trimble Field IQ

- Pump servo is selected
- Inc/Dec Proportional gain and/or Breakout to smoothen out the rate jumping